Material Safety Data Sheet

to comply with 29 CFR 1910.1200, OSHA's Hazard Communication Standard

E-127 Pure Tin Flux & Solder, 16-00

Section I:

Distributed By:
The Easthill Group
dba/ The Eastwood Company
263 Shoemaker Road
Pottstown, PA 19464

USA & Canada: 800-345-1178 Outside USA: 610-323-2200

Emergency Contact: Chem-Trec 800-424-9300

Revised 1/1/2009

Section II: Hazardous Ingredients/Identity information

```
Hazardous Component
                     CAS #
                               OSHA TWA
                                        ACGIH TWA
                                                        Other limits
              7440-31-5
                                2mg/M3
                                            2mg/M3
                                                            NE
  Tin
                                  1mg/M3
 + Zinc Chloride 7646-85-7
                                              1mg/M3
                                                                    7 %
                                                            NF.
  Ammonium Chloride 12125-02-9 10mg/M3 fume 10mg/M3 fume
                                                            NF.
        (as Zinc Ammonium Chloride)
```

Only those ingredients listed in this section have been determined to be hazardous as defined in 29CFR 1910.1200. An ingredient marked with an asterisk(*) is also listed in 29CFR 1910.1200(D) #4 as a known or suspected cancer hazard.

+ denotes a chemical regulated as toxic by the Environmental Protection Agency (EPA) as outlined in 40CFR Part 372 (section 313)

Section III: Physical/Chemical Characteristics

```
Boiling Point: 230 F Specific Gravity: 5.0
Vapor Pressure (mm Hg): NE Melting Point: NE
Vapor Density: NE Evaporation Rate
Solubility in water: appreciable (butyl acetate=1): < 1
Appearance and odor: silver grey paste odorless
```

Section IV: Fire and Explosion Hazard Data

```
Flash Point: NE Flammable limits lel: NE uel: NE Extinguishing media: all Special fire fighting procedures: use self-contained breathing apparatus Unusual Fire and Explosion Hazards: May release Hydrochloric acid, zinc chloride, zinc oxide.
```

Section V: Reactivity Data

```
Stability: STABLE Conditions to avoid: none
Incompatibility (materials to avoid): oxidizers, acids/bases, cyanides, sulfides, turpentine.
Hazardous Decomposition or Byproducts (incomplete Combustion): Hydrochloric acid,
ammonia, zinc oxide, zinc chloride.
Hazardous Polymerization: WILL NOT OCCUR Conditions to avoid: none
```

Section VI: Health Hazard Data

```
Routes of entry: Inhalation? yes Skin? No Ingestion? yes
```

Health Hazards (acute and chronic): Contact with material or fumes may cause skin, eye and respiratory tract irritation or burns. Severe fume inhalation can cause "metal fume fever" or pulmonary edema, which may not manifest for several hours after exposure. Ingestion can result in irritation or burning of digestive tract. Gross inhalation or ingestion can result in

```
death. LD50 (ZnCl2)(rat)=350mg/kg. May be mutagenic in lab animals. May cause sensitization.
Chronic exposures can result in permanent liver, kidney, and respiratory system damage.
Studies show that health risks may vary by individual. Minimize exposure as a precaution.

Carcinogenicity: not determined NTP? no IARC Monographs? no

Signs and symptoms of exposure: Inhalation-Nose & throat irritation, headache, dizziness, coughing, difficulty breathing. Ingestion-nausea, vomiting, cramps. Skin-redness, burning, rash, dryness. Eye-redness, burning, tearing, blurred vision.

Medical Conditions Aggravated by exposure: skin and respiratory conditions

Emergency first aid procedures:
   Skin: Flush with water immediately - Seek medical attention if necessary if necessary.
   Eyes: Flush with water for 15 minutes - Seek medical attention
   Ingestion: Do Not induce vomiting, give large amounts of water - Seek medical attention.
        Never give anything by mouth to an unconscious person.
   Inhalation: Remove to fresh air. Support respiration if required - Seek medical attention.
```

Section VII: Precautions for Safe Handling and Use

```
Steps to be taken if material is released or spilled: Vacuum, absorb or flush in to a chemical sewer. Do not use any method which will generate dust.

Waste Disposal Method: dispose of in accordance with all local state and federal regulations Other Precautions: Avoid skin & eye contact, inhalation & ingestion of fumes and material. Wash contaminated clothing before reuse, keep away from children, do not reuse container.
```

Section VIII: Control Measures

```
Respiratory Protection (type): Acid type/Metal fume/HEPA respirator for fumes over tlv. Ventilation: Local Exhaust preferred Special: none Mechanical: OK Other: NE Protective Gloves: impervious Eye Protection: Goggles or face shield Other Protective Clothing or Equipment: as required to avoid contact. Work/Hygienic Practices: Wash after use. Follow good industrial hygienic practices.
```

Section IX: Additional Information

```
DOT Classification: Non-Hazardous NFPA Classification (NFPA 325M,8th edition) (Health, Flammability, Reactivity): 1-1-0 Other: NE
```

The information and recommendations contained within this publication have been compiled from sources believed to be reliable and to represent the best information available to JOHNSON MANUFACTURING at the time of issue. No warranty, guarantee, or representation is made by JOHNSON MANUFACTURING nor does JOHNSON MANUFACTURING assume any responsibility in connection therewithin; nor can it be assumed that all acceptable safety measures or other safety measures may not be required under particular or exceptional conditions or circumstances.

NE = not established NA = not applicable

Form 303.54 Rev.B